

Casa Del Oro Elementary School



LA Testing
 5431 Industrial Drive, Huntington Beach, CA 92649
 Phone/Fax: (714) 828-4999 / (714) 828-4944
<http://www.LATesting.com> nlab@latesting.com

LA Testing Order: 332316224
 CustomerID: WEST60
 CustomerPO:
 ProjectID:

Attn: **David A Christy**
Western Environmental & Safety Tech.
7676 Hazard Center Drive
Suite 500
San Diego, CA 92108

Phone: (858) 271-1842
 Fax: (858) 271-1856
 Received: 9/18/2023 10:00 AM
 Collected: 9/12/2023

Project: **LA MESA SCHOOLS**

Analytical Results

Client Sample Description		Method	Parameter	Result	RL	Units	Prep Date & Analyst	Analysis Date & Analyst
CDO-01 RM 20 FOUNTAIN - FD				Collected:	10/10/2023	Lab ID:	332317738-0001	
200.8	Lead			<1.00	1.00	µg/L	10/11/2023 XL	10/12/2023 XL
CDO-02 RM 20 FOUNTAIN - FLUSH				Collected:	10/10/2023	Lab ID:	332317738-0002	
200.8	Lead			<1.00	1.00	µg/L	10/11/2023 XL	10/12/2023 XL
CDO-03 RM 10 FOUNTAIN - FD				Collected:	10/10/2023	Lab ID:	332317738-0003	
200.8	Lead			<1.00	1.00	µg/L	10/11/2023 XL	10/12/2023 XL
CDO-04 RM 7 FOUNTAIN - FD				Collected:	10/10/2023	Lab ID:	332317738-0004	
200.8	Lead			<1.00	1.00	µg/L	10/11/2023 XL	10/12/2023 XL
CDO-05 RM 4 FOUNTAIN - FD				Collected:	10/10/2023	Lab ID:	332317738-0005	
200.8	Lead			<1.00	1.00	µg/L	10/11/2023 XL	10/12/2023 XL
CDO-06 RM 24 FOUNTAIN - FD				Collected:	10/10/2023	Lab ID:	332317738-0006	
200.8	Lead			1.59	1.00	µg/L	10/11/2023 XL	10/12/2023 XL
CDO-07 RM 1 FOUNTAIN - FD				Collected:	10/10/2023	Lab ID:	332317738-0007	
200.8	Lead			1.32	1.00	µg/L	10/11/2023 XL	10/12/2023 XL
CDO-08 RM 1 FOUNTAIN - FLUSH				Collected:	10/10/2023	Lab ID:	332317738-0008	
200.8	Lead			<1.00	1.00	µg/L	10/11/2023 XL	10/12/2023 XL