Kempton Elementary School

LA Testing
5431 Industrial Drive, Huntington Beach, CA 92849
Phone/Fax (714) 828-4999 / (714) 828-4944
http://www.LATesting.com. hblab@latestin

LA Testing Order: CustomerID: CustomerPO: WEST60

ProjectID:

David A Christy Western Environmental & Safety Tech.

7676 Hazard Center Drive Suite 500 San Diego, CA 92108

Project: LA MESA SCHOOLS

Phone: Fax: Received: Collected: (858) 271-1842 (858) 271-1856 9/18/2023 10:00 AM 9/12/2023

Analytical Results

		Analytical Re	suits		
Client Sample Description	NO K-1 LOUNGE SINK-F/D		Collected:	Lab ID:	332317743-0021
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	8.92	1.00 µg/L	10/11/2023 XL	10/12/2023 XL
Client Sample Description	XI K-2 RM 18-SINK-F.D		Collected:	Lab ID:	332317743-0022
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.41	1.00 µg/L	10/11/2023 XL	10/12/2023 XL
Client Sample Description	xn K-3 RM 3-FOUNTAIN-F.A		Collected:	Lab ID:	332317743-0023
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.10	1.00 µg/L	10/11/2023 XL	10/12/2023 XL
Client Sample Description	xn K-04 RM 3-FLUSH-FOUNTAIN		Collected:	Lab ID:	332317743-0024
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	2.60	1.00 µg/L	10/11/2023 XL	10/12/2023 XL
Client Sample Description	on K-5 BLDG 6-EXT FOUNTAIN-I	RIGHT/RIGHT	Collected:	Lab ID:	332317743-0025
Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
METALS					
200.8	Lead	1.36	1.00 µg/L	10/11/2023 XL	10/12/2023 XL